FRA Presentation of BRC Leak June 2020 MOVING AMERICA FORWARD







RAIL

How did FRA find out?

Most of our transportation leaks or nonaccidental releases or NARs are discovered in transportation by inspectors, railroad officials, other modal regulators, or government reporting.

In this case, On June 4, 2020 FRA was forwarded a National Response Center (NRC) Report







Initial National Response Center (the other NRC!) Report on the incident



NRC#1278842.msg





The Actual NRC Description of the Incident.

CALLER IS REPORTING A RELEASE OF AN UNKNOWN AMOUNT OF RADIATION INTO THE ATMOSPHERE FROM AN UNKNOWN AMOUNT OF RADIATIVE RODS ON A RAIL CAR THAT CAUGHT FIRE INSIDE THE SRP RAIL YARD. THE FIRE IS ASSUMED TO BE STARTED BY FRICTION OF THE MATERIAL. THE FIRE HAS BEEN PUT OUT AT THIS TIME, AND IS BEING MONITORED INCASE OF REIGNITION



FRA's Immediate Response

- FRA made telephone contact to the Belt Railway
 Company(BRC) official, a railroad policeman, who submitted
 the details of the report for additional on-site details.
- He directed us to on-site response from Chicago Fire
 Department and the BRC's on site emergency contractor







Initial Response Questions from Emergency Responders

FRA received several questions from on-site responders regarding the appropriate methods to put the fire out.

Based on information they received from the railroad and the shipper, the responders were using water to put out the fire

Unfortunately, it was only temporary, and the fire reignited after a few hours and climbed back up to as much as 700-degrees





Shipping documents were unclear on the response

Based upon shipping papers provided in the early stages of the response, no one was aware of any obvious flammable materials, so they handled the response based upon the description of the material provided by the railroad and the shipper under ERG # 162, which is the guidance for a Radioactive Material, Low-Specific Activity (LSA). The response advises heavy water as a fire suppressor.

Early conversations with the shipper did not reveal anything of any relevance as to the source of the fire inside the car.



RAIL

MOVING AMERICA FORWARD

This cooling and reheating reportedly occurred several times. Something inside the car was still retaining heat and reigniting materials inside the car



RAIL

MOVING AMERICA FORWARD

A response contractor hired by the shipper came in and accessed the situation and made the decision to use sand to smother the fire coming from within the car and to reduce the heat. After several truckloads of sand, the cars temperature began to reduce to ambient temperature.

At that point discussions on transloading the material into other packages for removal has begun. It was decided that the contents was to be transferred into 20ft roll-off containers for highway transportation. The original destination of the material in this car, rejected the load after this incident.





Shipping Papers- How did the shipper described the contents of this car?

The specific contents of this car HKRX 50074 was described on the railroad waybill as containing;

UN 2912, Radioactive Materials, Low Specific Activity (LSA-1), 7 Radionuclides; CO-60, CS-134, CS, 137, U-234, Solid Oxide, Fissile Excepted, Exclusive Use.





Focused on Non-Hazmat Material in Car

The Nuclear Regulatory Commission 540/541 Low Level Waste Form also described the hazardous contents in the car the same, but we had the undeclared, or nonhazardous contents listed;

That included about 20 additional pages listing other nonregulated items by DOT but included in the Waste Disposal sheets attached in the document submitted.



Radioactive Material Tracking

The nonhazardous contents provided by the shipper included a large quantity of Zirc Tubes.

RANTA	G #	179 2	[4]4		Exial Other#	20.	- 8 - 0 / 7				
Date	Ship#	RAMTAG of Mater Packag d	Metais (stainles	ption: Le. Paper, Plastic, ess, carbon, etc.), Sol, Ri quipment, Ril, Etc.	, wood	Dose Rates (mR/hr) Contact 1 ft 1 m				Sign	
	o7-53		MISC BLAST		<u> </u>	.05.05		693	Drigher	. '	
1)			25 33	"	. 5	.15 .05		395	n -	<u>n</u>	
	15:0176	7 782	SIRC T	FURES	. 2	1 1		238			
1	07-026		.l	4	7	.07 .07		362			
	27.019	14-6142	1+	tr.	10]	1.07	1	362		,	
	07a 2df	156687	7 %	И		.07 -07	7	574	.a.		
		NS 265	P	ŋ	. 1	.07 -07		548			
		5.573	4.3	` <u></u>	. 07	.07 .07	/	550			
V	Ţ_	$\overline{\mathfrak{F}}$	>	•	07	.07.07		550			
1	07-1193	52 73		n	07	.07 .07		58.			
w)	07-193	561-3	•	*3	.05	.05.05	768	333	v	d	
44800	07-0214 167-216	5614	<u>~</u>	b	.05			1440	BUDYNE Unengetk	MADON	
Commen	ts	•									





Clarifying the Shipping Paper Entry

• After a few days into the response, FRA had some questions on the Zirc tubes entry and needed more details.

• We had a telephone conversation with the shipper who insisted that the Zirc tubes entry was in fact, Zircalloy and not Zirconium. They were very adamant that the rods were not Zirconium, especially not Zirconium Scrap and it no way hazardous, but they did convey that some of the rods were unused. We had several reasons to ask about Zirc Scrap.





Hazardous Materials Table in 49 CFR 172.101

Zirconium scrap	4.2 UN1932	111	4.2	IB8, IP21, N34, T1,	213	240	Forbidd en	Forbidd en	D	13, 148
				TP33, W31						





Hazardous Class 4.2 Spontaneously



Spontaneously Combustible-Spontaneous combustion or spontaneous ignition, as it is often called, is the occurrence of fire without the application of an external heat source.

Due to chemical, biological, or physical processes, combustible materials self-heat to a temperature high enough for ignition to occur.



RAIL

FRA Observations
during the
Transloading
Operations



During the transloading, FRA reported and photographed large metal machinery parts, including metal shop tables, drill presses and other objects as they were removed from the car. Large pieces of wood and the remains of other combustible debris were also removed along with the Zirc Rods.



RAIL MOVING AMERICA FORWARD



The Zirc Rods were dispersed throughout the gondola in no certain arrangement and were observed and photographed of various lengths. Some of the Zirc Rods were banded tighter and other looked to be used, flattened raggedly cut and ready for disposal. Because of the various degrees of the conditions of these rods, the Zirc Rod entry on the shipping paper became a question. At that point FRA began inquiring with the shipper and metallurgy experts for more details about the Zirc Rod entry.




RAIL

MOVING AMERICA FORWARD

Thanks to our friends at the Nuclear Regulatory Commission, The Pipeline & Hazardous Safety Administration, Illinois Commerce Commission,



Photo Identifying the Other Materials, Metal Machine Parts, in the car. Also see the Fire Suppression Hoses.









Photos from the response/transload





FRA – Office of Railroad Safety



U.S. Department of Transportation Federal Railroad Administration

Shipper Interview

- On Sept 2, 2020, at approximately 10:00 am, FRA met with the shipper, at their home office in Wampum PA.
- Our intent of the meeting was to discuss the fire in the gondola car at the BRC in Bedford Park (Chicago), IL.
- FRA were there to specifically discuss the contents of the car as presented on the 540/541 shipping documents and ask specific detailed questions as to the non-hazardous contents within the car to help determine the cause of the fire by reviewing both the hazardous and nonhazardous materials inside the car.





Shipper Interview- FRA Focus was on Zirc Rod Entry & Classification

FRA conducted the interview because the response reports along with observation from the FRA District 4 hazardous Materials personnel reporting the cars contents reigniting. Later as the heat issue was stabilized, and while the cars contents was being trans loaded into highway containers, the rods themselves were observed smoking and reigniting when exposed to the atmosphere.

The responder was observed standing over the car with water hoses. Because of these observations, we inquired for a more detailed description of the Zirc Rods entry on the shipping paper.





Shipper Responses to our Interview

The shipper continued to state that the rods inside the car were not Zirconium but Zircalloy Rods and not hazardous. He further stated that the rods had been cleaned of all shaving and loose debris. The shipper did admit that some of the rods had been cut and smashed in an earlier process for disposal, but no records were offered.

At that point FRA asked for any specific documents, shipping papers, invoices and any documents to indicate how the shipper classified the Zirc Rods listed as Zircalloy and not Zirc Scrap.

The shipper indicated that they had no documents to identify the rods as Zircalloy rods and used nothing to classify the material as Zircalloy.





NRC Import License dated 2010

FRA shared an NRC document dated August 31, 2010, with the shipper at this meeting. The document was an import license to move metals and other radiological materials from Mississauga Metals and Alloys (MM&A) in Canada to Energy Solutions in Clive, UT for final disposal with a mid-point stop at the shipper's location in Wampum, PA. Several entries in the document included various metals including Zirconium and Zirconium Scrap. The shipper claimed they had never seen the document.





Explaining the NRC Import License Document

- The materials were radiological waste and other metals and materials from US sites to Canada. The company Mississauga Metals in Canada had a fire in 2009 and was forced by the Canadian government to remove the materials from their site.
- This import application document, the NRC Form 7, docket #11005875
 the "Application for NRC Export/Import License, Amendment, or
 Renewal", dated August 31, 2010, details by site specific waste code and
 material list where the materials originated from in the US by Waste
 Code and an inventory list by description and total weight coming from
 each location back to the US.





Shipper Responsibility to Classify the Materials in a DOT Shipment

Since the shipper was so adamant that the Zirc Rods were nonhazardous, we did ask the shipper to search their archives to on any paperwork, Safety Data Sheets (SDS), shipping papers or other documentable testing or justification for their Zircalloy classification on this shipping paper.

The shipper did state the they have an off site storage facility and would look for any documentation that would relate to the 2010 shipment date of the MM&A import license document that we presented to them.





NRC Document Research

 FRA discovered an additional document, specifically a letter, dated November 15, 2010, from the NRC addressed to the State of Pennsylvania. The letter was written specifically to ask Pennsylvania to grant an application for an import license to Oregon Specialty Metals (IWO28) to allow materials from Canada to come into Pennsylvania, specifically Oregon Metals in Wampum, PA (*same physical address for shipper*) for waste processing before being sent to Energy Solutions in Clive, UT.





NRC Historical Documents

 A separate and third document dated January 13, 2011, was obtained from the NRC by FRA on December 19, 2020. This document was a written response from Oregon Specialty Metals that described the relationship between Oregon Specialty Metals and the shipper.





Who was Oregon Specialist Metals?

Oregon Specialty Metals is the business unit of MMA and was created because the NRC regulations required a US registered entity for processing waste.

The document further describes that all processes will occur under the shippers Pennsylvania License with the NRC and that all the wasted processes for the incoming materials will occur on the shippers property. These processes included cutting, splitting and smashing the remaining Zirconium Scrap rods.





The relationship between Oregon Metals and the shipper

 This document clarifies that the shipper had access to all records of incoming materials, the processes conducted and the final analysis of those materials before shipments to Energy Solutions in Clive, UT.





Remembering the cut Zirconium Rods

 Based upon the SDS sheets for Zirconium Rods, and/or (Zircalloy Rods), there is a "Special Precautions Section" that indicates this material, especially "cut" sections, can be pyrophoric and can be ignited. There was no special handling instructions provided from the shipper with the loading of these Zirconium rods.





SDS Sheets


 That section also indicates not to use water. Water was utilized to extinguish the fire created when the contents of the rail car was unloaded that created an oxygen rich environment.

• There were no special handling instructions provided from the shipper or conveyed on the shipping documents with the shipping of these Zircalloy rods. The Zirc Rods were found piled on top of each other in the car when the transloading/remediation began.





Photograph of the loaded car provided by the shipper before the fiberglass lid was applied







Zirconium Properties

 Dust clouds of larger particle size can be readily ignited if an ignition source is present, and such explosions can occur in atmospheres of carbon dioxide or nitrogen as well as in air.
 Spontaneous heating and ignition are also possibilities with scrap chips, borings, and turnings if fine dust is present.





Conclusions

- Although zirconium rods pose no danger of reaction if properly packaged and the rods themselves, when they have not been altered, but sufficient evidence was found that many of the zirconium rods were altered by an internal process at the shipper's location and loaded into this car.
- Based upon the information collected during this investigation by FRA, the shipper had the information to properly know that Zirconium Rods, Zirc Scrap, Molybdenum and other metals were being loaded into this car.



U.S. Department

Conclusions

 This investigation also proved that the shipper improperly loaded this car by allowing the Zirconium Rods to interact with other Zirconium Rods and other metal objects, despite information of the SDS for this material. This metal-to-metal contact created friction through movement in transportation that caused the rods to create filings. Those Zirconium filings are the most volatile and they created the sparks that ignited the combustible dunnage that was loaded in the void spaces between the rods and other metal objects in the car.

Moving America Forward

FRA Recommendations

 We are recommending that packaging standards be developed for Zirconium, Zircalloy and all other derivatives of Zirconium that demonstrates pyrophoric properties be required to be separated and/or blocked and braced by regulation so they cannot interact with other Zirconium or other metals while in transportation.





FRA Recommendations- Contd...

 Based on the properties of Zirconium, it is inherently not flammable and resistive to high heat and used in the Nuclear industry because of these properties, but when ground or rubbed in such a way allowing the interaction created by metal to metal contact it created very volatile small filing from the Zirconium and Zircalloy.





In Conclusion

 By creating packaging standards for such metals, it would eliminate the possibility of the metals interacting with each other, and the pyrophoric event that created the nonaccidental release associated with this package.





